![CalAmp®]

PRODUCT BULLETIN

August 15, 2013

Effective Immediately: (For internal and external distribution)
Fusion Firmware (v1.1.7) Update and Maintenance Release

Summary
This product bulletin serves as a notice that Fusion has an updated version of Firmware (v1.1.7).

Release Date: August 15, 2013

Product Information
Fusion, CalAmp's most advanced router, providing mission critical broadband connections for Fixed and Mobile Applications is now manufactured with FW version v1.1.7. Factory new units will be shipped with v1.1.7, offering a ready to use configuration.

This release enables new features: (Complete details can be found in the FW release notes)
- LTE handoff improvements, including an updated release of radio module FW
- Concurrent WiFi to support access point and client mode
- Radio module Firmware updates Over the Air (FOTA)

In addition, the FW maintenance release package is commercially available for updating Fusion to the latest v1.1.7 release via the following methods:

- DeviceOutlook: Leveraging DeviceOutlook's FOTA (FW Over-the-Air) services capabilities and ready to use FW library, making updating one, or many, Fusions simple and efficient
- Direct Update: Manually updated the unit by uploading the FW package to the Fusion and executing an update

Please refer to the Device Firmware Help Portal for instructions and Device FW files to complete the Fusion upgrades.
www.calamp.com/devicefirmware/index.html

Our courteous technical support staff can provide guidance on the correct process to update Fusion to the current release and answer any questions in regards to updating FW on Fusion.

There are two ways to contact customer and technical support.
Phone: Call (507) 833-8819 select for 24/7 customer support
Online: wngsupport@calamp.com

For more information on CalAmp products, please visit www.CalAmp.com.