

## Fusion Multi-Network Router Transition to End of Life

EOL NUMBER  
180621

## Product Notice: Fusion Router Transition to End of Life – [EOL-180615]

**PCN Type:** End of Life Notice

**Reason:** Market Drivers and Decreasing Demand

### CalAmp Fusion Transition to End of Life (EOL)

This letter serves as notice CalAmp has reached a transition point in the lifecycle of the Fusion multi-network routers and all associated variants. Due to market drivers, lack of future component availability, as well as fluctuations in demand, Fusion routers (all SKUs listed) can no longer be supported in consistent run rate volumes necessary to support consistent stock. As a result, continuation of the products would result in long lead times and increased costs to CalAmp and to our customers, therefore effective continuation of these products shall end.

### Effective Changes

All Fusion Single-Radio, Single-Radio with Wi-Fi, Dual-Radio, and Dual-Radio with Wi-Fi variants are subject to this EOL notice. For all detailed part numbers and successor options, please refer to the comprehensive index at the bottom of this notice.

### Effectivity

CalAmp will try to accommodate all customer requests; however, once current stock levels have been depleted, the Fusion router will no longer be available to order.

Refer to the following table for the EOL timeline of product purchase opportunity:

Notice	Date	Remarks
Last Time Buy	09/25/2018	All orders for EOL SKUs are due by this date and are <b>non-cancelable</b> and <b>non-returnable</b> (NCNR)
Last Time Ship	12/21/2018	All orders placed on LTB date must ship no later than this date.

### End of Warranty

CalAmp will continue to offer our standard warranty for these products through the final shipments, including honoring existing extended warranties. RMAs will be accepted for 1 year past the last shipment date.

### End of Support

Product Technical Support will continue for 3 years past the last shipment date.

## Fusion Multi-Network Router Transition to End of Life

EOL NUMBER  
180621

## Contact and Support

CalAmp appreciates and values your continued business relationship and we look forward to your future interest in our outstanding product portfolio. Please contact your CalAmp sales or support representative with any questions you may have.

<https://www.calamp.com/support/> Email: [productsupport@calamp.com](mailto:productsupport@calamp.com)

## Part Numbers Affected Index

CalAmp is positioned to officially discontinue the following part numbers:

EOL P/N*	Description	Successor P/N	Replacement Type <sup>1</sup>
1409303000	FUSION LTE ROUTER, B14, GPS	N/A	No Replacement
1409303100	FUSION LTE ROUTER, B14, WIFI, GPS	N/A	No Replacement
140930G000	FUSION LTE ROUTER, B12/GPS	N/A	No Replacement
140930G100	FUSION LTE ROUTER, B12/WIFI/GPS	N/A	No Replacement
140930K000	FUSION LTE ROUTER, B20 SW, EU VERSION, GPS	VG5530-LEU-M-GEN	Functional Replacement
140930K100	FUSION LTE ROUTER, B20 SW, EU VERSION, WIFI, GPS	VG5530-LEU-M-GEN	Functional Replacement
1409320000	FUSION LTE ROUTER, B13 VERIZON, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409320100	FUSION LTE ROUTER, B13 VERIZON, WIFI, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409323000	FUSION LTE ROUTER, DUAL RADIO, B13 AND B14, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409323100	FUSION LTE ROUTER, DUAL RADIO, B13 AND B14, WIFI, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409324000	FUSION LTE ROUTER, DUAL RADIO, B13 AND B17, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409324100	FUSION LTE ROUTER, DUAL RADIO, B13 AND B17, WIFI, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
140932G000	FUSION LTE ROUTER, DUAL RADIO, B12/B13/GPS	VG5530-LVZ-M-VZAT	Functional Replacement
140932G100	FUSION LTE ROUTER, DUAL RADIO, B12/B13/WIFI/GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409340000	FUSION LTE ROUTER, B17 AT&T, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409340100	FUSION LTE ROUTER, B17 AT&T, WIFI, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409343000	FUSION LTE ROUTER, DUAL RADIO, B17 AND B14, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409343100	FUSION LTE ROUTER, DUAL RADIO, B17 AND B14, WIFI, GPS	VG5530-LVZ-M-VZAT	Functional Replacement

## Fusion Multi-Network Router Transition to End of Life

EOL NUMBER  
180621

140934G000	FUSION LTE ROUTER, DUAL RADIO, B12/B17/ GPS	VG5530-LVZ-M-VZAT	Functional Replacement
140934G100	FUSION LTE ROUTER, DUAL RADIO, B12/B17/WIFI/GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409350000	FUSION LTE ROUTER, ROGERS, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1409350100	FUSION LTE ROUTER, ROGERS, WIFI, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
14093KK000	FUSION LTE ROUTER, DUAL B20 SW, EU VERSION, GPS	VG5530-LEU-M-GEN	Functional Replacement
14093KK100	FUSION LTE ROUTER, DUAL B20 SW, EU VERSION, WIFI, GPS	VG5530-LEU-M-GEN	Functional Replacement
190930G000	FUSION LTE ROUTER, B14/B12/B4 GDB, GPS	N/A	No Replacement
190930G100	FUSION LTE ROUTER, B14/B12/B4 GDB, WIFI, GPS	N/A	No Replacement
190930H010	OEM FUSION ROUTER, B14, GPS, 2 YR WARRANTY	N/A	No Replacement
190930H110	OEM FUSION ROUTER, B14, WIFI, GPS, 2 YR WARRANTY	N/A	No Replacement
190930J100	FUSION LTE ROUTER, B20 GD, UE VERSION, WIFI, GPS	VG5530-LEU-M-GEN	Functional Replacement
1909320010	OEM FUSION ROUTER, B13, GPS, 2 YR WARRANTY	VG5530-LVZ-M-VZAT	Functional Replacement
1909320110	OEM FUSION ROUTER, B13, WIFI, GPS, 2 YR WARRANTY	VG5530-LVZ-M-VZAT	Functional Replacement
190932G000	FUSION LTE ROUTER, DUAL RADIO, B14/B12/B4 AND B13, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
190932G100	FUSION LTE ROUTER, DUAL RADIO, B14/B12/B4 AND B13, WIFI, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
190932H010	OEM FUSION ROUTER, B13 AND B14, GPS, 2 YR WARRANTY	VG5530-LVZ-M-VZAT	Functional Replacement
190932H110	OEM FUSION ROUTER, B13 AND B14, WIFI, GPS, 2 YR WARRANTY	VG5530-LVZ-M-VZAT	Functional Replacement
1909340000	FUSION LTE ROUTER, B17 VTEL, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1909340010	OEM FUSION ROUTER, B17, GPS, 2 YR WARRANTY	VG5530-LVZ-M-VZAT	Functional Replacement
1909340100	FUSION LTE ROUTER, B17, VTEL, WIFI, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
1909340110	OEM FUSION ROUTER, B17, WIFI, GPS, 2 YR WARRANTY	VG5530-LVZ-M-VZAT	Functional Replacement
190934G000	FUSION LTE ROUTER, DUAL RADIO, B14/B12/B4 AND B17, GPS	VG5530-LVZ-M-VZAT	Functional Replacement

## Fusion Multi-Network Router Transition to End of Life

EOL NUMBER  
180621

190934G100	FUSION LTE ROUTER, DUAL RADIO, B14/B12/B4 AND B17, WIFI, GPS	VG5530-LVZ-M-VZAT	Functional Replacement
190934H010	OEM FUSION ROUTER, B17 AND B14, GPS, 2 YR WARRANTY	VG5530-LVZ-M-VZAT	Functional Replacement
190934H110	OEM FUSION ROUTER, B17 AND B14, WIFI, GPS, 2 YR WARRANTY	VG5530-LVZ-M-VZAT	Functional Replacement

(\*)Includes all customer specific SKU/configurations

[1] *Functional replacement products may contain additional or different features/specifications – applicable only to Fusion variants supporting B13 and/or B17 (VG5530-LVZ-M-VZAT) and B20 (VG5530-LEU-M-GEN)*