



## DM-CTC 3.16 Release Notes

---

## 3.16 FEATURE SET

### Radio Firmware Version Fix

Radio Firmware version is now correctly displayed.

### App ID 445 (VBUS) Removed for TTU2830MB Device Type

Relevant APIs updated to reflect the change.

### Performance Improvements

Various load management enhancements.

---

## SUPPORTING YOUR SOLUTION EVERY TIME. ALL THE TIME.

CalAmp does more than provide you with application services – we also supply you with an always-available resource for attention, answers, and insights if you have questions about your solution.

CalAmp's Technical Support team stands beside you to ensure that any concerns you have with any element of your solution – application, hardware, or operations – are addressed quickly and completely.

You can contact the Technical Support team via email at [solutionsupport@calamp.com](mailto:solutionsupport@calamp.com).